







**Kenney Cottage
Berkeley, CA**

Image	Date	Description
 <p data-bbox="396 632 516 663">Photo1.jpg</p>	4/2002	View of the west wall of Kenney Cottage, looking northeast. When Kenney Cottage was moved to University Avenue in 1906, it was elevated and storage rooms were built below the dwelling. The portion of the building located behind the trailer is a non-historic addition.
 <p data-bbox="396 997 516 1029">Photo2.jpg</p>	4/2002	Detail view of the bolted sill and corner post connection (to the left of center). The siding to the left of the corner post is cladding on the addition, and the recessed siding to the right of the corner post is original to Kenney Cottage.
 <p data-bbox="396 1362 516 1394">Photo3.jpg</p>	4/2002	Detail view of one of the original porch posts at the left and the porch ceiling above. This historic fabric was encased in stucco and uncovered during the process of documenting the building.
 <p data-bbox="396 1728 516 1759">Photo4.jpg</p>	4/2002	View of the main room in Kenney Cottage, looking north toward the rear wing. Selective demolition of non-historic wall finishes revealed that this room was originally divided into two smaller rooms and exposed the post and board construction at the back wall.

**Kenney Cottage
Berkeley, CA**

Page 2 of 2

Image	Date	Description
 <p>Photo5.jpg</p>	4/2002	View of the post and board construction in the south, first floor bedroom and one of the original two-over-two light windows.
 <p>Photo6.jpg</p>	4/2002	Detail view of one of the original two-over-two light windows, set between two of the posts that make up the post and board wall construction.